

Figure 3.9 Rotary knob wet/dry

Wet Turn the rotary knob (A) to the end-limit "wet" = 100% operating with saturated steam

Dry Turn the rotary knob (A) to the end-limit "dry" = 100% operating with dry steam

The intensity of the mixing ratio of the steam function will be regulated by turning the rotary knob (A) as 0-100%. The mixing ratio can also be adjusted during the steam operation.

3.10 Safety valve




Fig. 3.10 safety valve (A)



See chapt. 7.5.